DIFFUSION TRANSFER SYSTEM

Z3APRIL 1948 NI

NUMBERS DENOTE STEPS IN THE PROCESSING OPERATION. ARROWS DENOTE MATERIAL MOVEMENT.

A-TAKE O.N. INTO SHELTER TO BREAKDOWN AREA.

2.-BREAK-DOWN INTO 500 FT. ROLLS.

3.- PLACE IN PASSBOX OR ONTO TRISPIN.

4.- LOAD BIMAT FILM ONTO TRISPIN.

5.- LAMINATE O.N. & BIMAT.

6.- PLACE LAMINATE IN PASSBOX FOR PROCESSING.

7.- LOAD ON.-BIMAT LAMINATE ONTO PENTASPIN.

B.-LOAD DESIMAT TAPE ONTO PENTASPIN.

9- LOAD COVERSHEET ONTO PENTASPIN.

10. - DELAMINATE O.N. FROM BIMAT POSITIVE - AND

11. - LAMINATE O.N. WITH DESIMAT TAPE - AND

12- LAMINATE BIMAT POSITIVE WITH COVERSHEET.

13. - PLACE FINISHED BIMAT POSITIVE ON STORAGE SHELF.

14 - PLACE O.N. - DESIMAT TAPE LAMWATE IN PASSBOX.

15 .- LOAD O.N. - DESIMAT TAPE LAMINATE ONTO TRISPIN.

16. - DELAMINATE DESIMAT TAPE FROM O.N.

17.-PLACE USED DESIMATE TAPE ON STORAGE SHELF.

18 - PLACE FINISHED O.N. IN PASSBOX.

19.-LOAD O.N. ONTO DRIAGARA.

20. - LOAD DRIMAT FILM ONTO DRIAGARA.

ZI.- LOAD DUPE STOCK ONTO DRIAGARA.

ZZ-PRINT DURE - AND

23.- LAMINATE PRINTED DURE AND DRIMAT FUM.

24. - PLACE DUPE-DRIMAT LAMINATE ON STORAGE SHELF.

25 - PLACE O.N. IN PASSEOK.